

DOWNLOAD THE CONTROL LIST FOR PRODUCT NO. : 5790

**Product details:** T-shirt sport en coton 500 – Femmes**Year of purchase:** 2022**Product condition:** Excellent**Seller description:** Un t-shirt multisport pour vos activités préférées et la vie quotidienne.

Inspection points	What to inspect	Inspection process	Criticality	Requirement	Inspection points passed
Overall control	Product Visual inspection	Visually check the condition of the product.	-	The product complies with the rules of use, safety and hygiene.	--- true

**This product obtained the Inspected Product label**

Inspected on 11 May 2022 by Francis

In receiving this document, you acknowledge that you are aware of and are responsible for any potential problems identified with the inspected product. The product inspection service cannot fully guarantee the product's safety if it used after the inspection.